

Pittsburg Unified School District

1

CONSTRUCTION UPDATE

FACILITIES PLANNING
& MANAGEMENT

January 10, 2018

WILLOW COVE ELEMENTARY SCHOOL

2



View of Roofing Replacement Work @ Building E - Looking Northwest

WILLOW COVE ELEMENTARY SCHOOL

3



View of Roofing Replacement Work @ Building E - Looking Northeast

WILLOW COVE ELEMENTARY SCHOOL

4



View of Demolition Completion & New Framing Inside of Building E – Looking Northeast toward Former Kitchen

WILLOW COVE ELEMENTARY SCHOOL

5



View of Demolition Completion Inside of Building E - Looking Northwest

WILLOW COVE ELEMENTARY SCHOOL

6



View of Demolition Completion Inside of Building E - Looking Southwest

WILLOW COVE ELEMENTARY SCHOOL

7



View of Demolition Completion & New Framing in Former Kitchen Inside of Building E

QUESTIONS?